



## Container Inspection Report

Container No	Container Size	Container Type	CSC MGF Date	Type
WHSU2242199	40'	General Purpose (GP)	01/02/2000	Laden/Pick Up

S.No	Location	Photos	Remarks
1	Roof Top	1	
2	Front Panel & Rail	0	No Damage
3	Left Side Panel	1	DENT
4	Door & Locking Assembly	0	
5	Right Side Panel & Rail	0	
6	Interior & Floor	0	
7	Under Carriage	1	SOME THING IS MISSING

Roof Top

.....

**Damages:**



Front Panel & Rail

.....

**Damages:**

Left Side Panel

.....

**Damages:**





## Container Inspection Report

Door & Locking Assembly

**Damages:**

Right Side Panel & Rail

**Damages:**

Interior & Floor

**Damages:**

Under Carriage

**Damages:**



Name of Inspector / Surveyor

: Sudhakar Reddy

Place of Inspection

: Union Square, CA, United States (WSPORT)

Date & Time

: 24.Jun.2021 @ 01:36 PM

GPS Location

